

Temporary ROIL Multiplier increases

Refer sections 4.4, 12.18 of the MPOC

Period (start)	Period (end)	Welded Point(s)	Value	Reason
13/12/2017	13/12/2017	Tikorangi #3 (Receipt)	4.0	Support for restoration of conditions after station trip
11/12/2017	11/12/2017	Tikorangi #3 (Receipt)	5.0	Support for restoration of conditions after station trip
01/11/2017	01/11/2017	Oaonui	18.5	Support for planned plant outage
27/10/2017	27/10/2017	Tikorangi #3 (Receipt)	6.0	Support for restoration of conditions after station trip
27/10/2017	27/10/2017	Tikorangi #2	4.0	ditto
22/10/2017	22/10/2017	Ngatimaru Rd (Receipt)	9.0	Support for restoration of conditions after station trip
05/10/2017	05/10/2017	Oaonui	21.0	Support for planned plant outage
28/09/2017	28/09/2017	Tikorangi #2	4.1	Support for restoration of conditions after station trip
06/09/2017	06/09/2017	Ngatimaru Rd (Delivery)	7.0	Support for restoration of conditions after station trip
30/08/2017	30/08/2017	Tikorangi #3 (Receipt)	7.5	Support for restoration of conditions after station trip
16/08/2017	16/08/2017	Tikorangi #3 (Receipt)	2.0	Support for restoration of conditions after station trip
20/07/2017	20/07/2017	Tikorangi #3 (Receipt)	4.0	Support for restoration of conditions after station trip
20/07/2017	20/07/2017	Tikorangi #2	2.0	ditto
26/06/2017	26/06/2017	Oaonui	8.0	Support for restoration of conditions after station trip
25/06/2017	25/06/2017	Oaonui	13.5	Support for restoration of conditions after station trip
19/06/2017	19/06/2017	Oaonui	8.5	Support for restoration of conditions after station trip
19/06/2017	19/06/2017	Tikorangi #2	3.5	Support for restoration of conditions after station trip
01/06/2017	01/06/2017	Ngatimaru Rd (Receipt)	10.0	Support for restoration of conditions after station trip
31/05/2017	31/05/2017	Ngatimaru Rd (Receipt)	30.0	Support for restoration of conditions after station trip
01/05/2017	15/05/2017	Ngatimaru Rd (Delivery)	4.6	Support for planned plant outage
18/04/2017	18/04/2017	Frankley Road	3.0	Incomplete data for some allocation gates behind the Welded Point.
18/04/2017	18/04/2017	Rotowaro	2.0	ditto
17/04/2017	17/04/2017	Oaonui	2.0	Support for restoration of conditions after station trip
02/04/2017	02/04/2017	Ngatimaru Rd (Receipt)	3.5	Support for restoration of conditions after station trip
24/03/2017	24/03/2017	Frankley Road	12.2	Site communication lost
19/03/2017	19/03/2017	Oaonui	5.0	Support for restoration of pipeline conditions.
18/03/2017	18/03/2017	Oaonui	15.0	Support for restoration of pipeline conditions.
14/03/2017	17/03/2017	Oaonui	25.0	Support for planned plant outage
10/02/2017	10/02/2017	Oaonui	5.0	Support for restoration of conditions after station trip
30/01/2017	30/01/2017	Oaonui	23.0	Support for planned plant outage
25/01/2017	25/01/2017	Oaonui	13.0	Support for restoration of conditions after station trip
02/01/2017	03/01/2017	Ngatimaru Rd (Receipt)	2.0	Support for restoration of pipeline conditions.
02/01/2017	03/01/2017	Tikorangi #2	6.5	ditto
25/12/2016	25/12/2016	Tikorangi #3 (Receipt)	3.5	Support for restoration of conditions after station trip
25/12/2016	25/12/2016	Tikorangi #2	2.0	ditto
20/12/2016	20/12/2016	Oaonui	17.0	Support for restoration of pipeline conditions.
15/12/2016	15/12/2016	Ngatimaru Rd (Receipt)	6.0	Support for restoration of conditions after station trip
15/12/2016	15/12/2016	Tikorangi #3 (Receipt)	2.0	ditto
15/12/2016	15/12/2016	Tikorangi #2	2.5	ditto
23/11/2016	23/11/2016	Frankley Road	1.6	Support linepack management
23/11/2016	23/11/2016	Pokuru	2.0	ditto
15/11/2016	15/11/2016	Oaonui	17.0	Support for restoration of conditions after station trip
01/11/2016	01/11/2016	Faul Road	2.0	Support for planned plant outage
20/10/2016	20/10/2016	Ngatimaru Rd (Receipt)	12.0	Support for restoration of conditions after station trip
20/10/2016	20/10/2016	Tikorangi #2	3.0	ditto
15/10/2016	15/10/2016	Oaonui	12.5	Inability to Access OATIS.
15/10/2016	15/10/2016	Frankley Road	11.7	ditto
15/10/2016	15/10/2016	Rotowaro	4.1	ditto
18/09/2016	18/09/2016	Ngatimaru Rd (Receipt)	5.0	Support for planned plant outage
15/09/2016	15/09/2016	Oaonui	7.0	Support for planned plant outage
01/09/2016	01/09/2016	Frankley Road	8.3	Support for Pigging.
01/09/2016	01/09/2016	Rotowaro	8.3	ditto
31/08/2016	31/08/2016	Frankley Road	7.0	Support for Pigging.
31/08/2016	31/08/2016	Rotowaro	7.0	ditto
05/08/2016	06/08/2016	Tikorangi #3 (Receipt)	3.0	Support for restoration of conditions after station trip
05/08/2016	06/08/2016	Tikorangi #2	2.3	ditto
27/07/2016	27/07/2016	Ngatimaru Rd (Receipt)	7.0	Support for planned plant outage
26/05/2016	26/05/2016	Tikorangi	5.0	Support for restoration of conditions after station trip
26/05/2016	26/05/2016	Tikorangi #2	5.0	ditto
26/05/2016	26/05/2016	Ngatimaru Rd (Receipt)	5.0	ditto
24/05/2016	24/05/2016	Oaonui	3.5	Accommodate Oaonui support during the Critical Contingency event
17/05/2016	17/05/2016	Tikorangi	5.5	Support for plant re-start
17/05/2016	17/05/2016	Tikorangi #2	8.0	ditto
17/05/2016	17/05/2016	Tikorangi #3 (Receipt)	8.0	ditto
17/05/2016	17/05/2016	Ngatimaru Rd (Receipt)	12.0	ditto
07/05/2016	07/05/2016	Tikorangi #2	2.6	Support for plant re-start
27/04/2016	27/04/2016	Tikorangi #2	7.0	Support for plant re-start
27/04/2016	27/04/2016	Tikorangi #3 (Receipt)	7.7	ditto
20/04/2016	20/04/2016	All Large Physical WP	4.0	OATIS outage affecting intra-day 4 cycle
10/04/2016	10/04/2016	Huntly Power Station	3.0	OATIS outage affecting intra-day cycles
10/04/2016	10/04/2016	Turangi Mixing Station	3.0	ditto
10/04/2016	10/04/2016	Tikorangi #3 (Receipt)	4.0	
10/04/2016	10/04/2016	Frankley Road	9.0	
10/04/2016	10/04/2016	Rotowaro	4.0	
05/04/2016	05/04/2016	Ngatimaru Road (Receipt)	5.2	Support for restoration of conditions after station trip
20/03/2016	20/03/2016	Oaonui	13.5	Support for planned Pohokura PPB re-start
20/03/2016	20/03/2016	Tikorangi #2	25.0	ditto
19/03/2016	19/03/2016	Ngatimaru Road (Receipt)	24.0	Support for planned Pohokura PPB re-start
19/03/2016	19/03/2016	Oaonui	21.0	ditto
19/03/2016	19/03/2016	Tikorangi #2	4.5	ditto
10/03/2016	19/03/2016	Ngatimaru Road (Receipt)	4.0	Support for planned Depressurisation/Represurisation of pipeline
09/03/2016	10/03/2016	Ngatimaru Road (Delivery)	23.0	Support for planned Depressurisation/Represurisation of pipeline
09/03/2016	10/03/2016	Faul Road	23.0	Support for planned Depressurisation/Represurisation of pipeline
04/03/2016	09/03/2016	Ngatimaru Road (Receipt)	10.0	Support for planned Depressurisation/Represurisation of pipeline
03/03/2016	03/03/2016	Tikorangi Mixing Station	9.0	Support for restoration of conditions after station trip
03/03/2016	03/03/2016	Tikorangi #2	9.0	ditto
29/02/2016	29/02/2016	Tikorangi Mixing Station	5.0	Support for restoration of conditions after station trip
29/02/2016	29/02/2016	Tikorangi #2	5.0	ditto
29/02/2016	29/02/2016	Tikorangi #3 (Receipt)	5.0	ditto
04/02/2016	05/02/2016	Frankley Road	8.4	ID4 nominations of some Shippers for 04/02/2016 were incorrect due to an OATIS system error.
04/02/2016	05/02/2016	Rotowaro	5.2	ditto
21/01/2016	21/01/2016	Oaonui	11.0	Oaonui production facility return to service from Force Majeure shutdown.
21/01/2016	21/01/2016	Ngatimaru Road (Receipt)	5.0	ditto
10/01/2016	10/01/2016	Ngatimaru Road (Receipt)	8.0	Support for planned Pohokura PPB re-start
10/01/2016	10/01/2016	Tikorangi #2	4.0	ditto
16/12/2015	16/12/2015	Tikorangi Mixing Station	3.5	Support for restoration of conditions after station trip
16/12/2015	16/12/2015	Tikorangi #2	8.5	ditto
16/12/2015	16/12/2015	Tikorangi #3 (Receipt)	3.5	ditto
16/12/2015	16/12/2015	Ngatimaru Road (Receipt)	11.0	Support for planned Pohokura PPB outage
05/12/2015	05/12/2015	Ngatimaru Road (Receipt)	20.0	Facilitation for approved OPN
20/11/2015	20/11/2015	Oaonui	20.0	Prepacking line for approved OPN on 21/11/2015
29/10/2015	30/10/2015	Oaonui	13.0	Prepacking line for approved OPN on 30/10/2015
28/10/2015	30/10/2015	Ngatimaru Road (Receipt)	5.0	Approved maintenance-high flow trial
18/10/2015	18/10/2015	Pirongia	2.5	ditto
17/10/2015	17/10/2015	Pirongia	3.0	ditto
16/10/2015	16/10/2015	Pirongia	3.5	ditto
15/10/2015	15/10/2015	Pirongia	4.0	ditto
14/10/2015	14/10/2015	Pirongia	4.0	Incorrect OI information in OATIS from 11/09/2015
05/10/2015	05/10/2015	Frankley Road	4.5	Misleading flow data published on BGIX; primary information source confusion