

Temporary ROIL Multiplier increases

Refer sections 4.4, 12.18 of the MPOC

Period Start	Period End	Wicket Points	Value	Reason
19/05/2022	20/05/2022	Robrow	9.0	Northern Pressure Temporarily Reduced
19/05/2022	14/06/2022	Onara	2.0	Support operational issues
12/05/2022	13/05/2022	Onara	1.5	To support operational issues
12/05/2022	13/05/2022	Franklin Road	1.5	To support operational issues
01/05/2022	02/05/2022	Onara	3.0	Support gas specification issue
25/04/2022	25/04/2022	Onara	3.0	To support operational issues after outage trip
25/04/2022	26/04/2022	Onara	2.0	Support operational issues
25/04/2022	25/04/2022	Napier Rd	2.0	Support operational issues with power outage
23/04/2022	23/04/2022	Napier Road (Receipt)	6.0	Support operational issues with power outage
23/04/2022	23/04/2022	Therang 3	6.0	Support operational issues with power outage
15/04/2022	16/04/2022	Onara	2.0	Support well start up issues
03/04/2022	04/04/2022	Therang 3	2.5	Support system issue with wellhead sealing
03/04/2022	04/04/2022	Napier Rd (Delivery)	2.0	Support well start up issues
21/03/2022	01/04/2022	Full Road	1.5	Support start control issues
21/03/2022	21/03/2022	Onara	3.0	Support well start up
21/03/2022	28/03/2022	Therang 3	3.0	To support operational issues
21/03/2022	28/03/2022	Therang 3	3.0	Support well returns to service from planned maintenance
19/03/2022	18/03/2022	Onara	8.0	Support unplanned outage 20/03/2022
19/03/2022	18/03/2022	Onara	3.0	Support well start up issues
16/03/2022	16/03/2022	Onara	5.0	Support well start up issues
09/03/2022	09/03/2022	Onara	2.5	Support operational well start up issues
08/03/2022	09/03/2022	Onara	3.5	To support operational issues
08/03/2022	11/03/2022	Onara	3.0	Support operational well shutdown
14/02/2022	15/02/2022	Napier Road (Receipt)	4.0	To support well issues
13/02/2022	14/02/2022	Therang 2	2.0	To support unplanned outage & asset
13/02/2022	14/02/2022	Onara	2.0	To support operational issues
13/02/2022	14/02/2022	Napier Road (Receipt)	2.0	To support operational issues
11/02/2022	12/02/2022	Onara	3.5	To support operational issues
11/02/2022	12/02/2022	Therang 3	2.0	Support for service via MOP
10/02/2022	11/02/2022	Onara	6.2	To support operational issues
04/02/2022	05/02/2022	Therang 3	4.0	Support for well start issues
03/02/2022	04/02/2022	Onara	1.2	To support balancing activities after Pohokura outage
02/02/2022	03/02/2022	Napier Road (Receipt)	1.5	To support unplanned site outage after ESD day
02/02/2022	03/02/2022	Therang 2	6.0	To support unplanned site outage after ESD day
01/02/2022	02/02/2022	Napier Road (Receipt)	18.0	To support site outage
01/02/2022	02/02/2022	Therang 2	6.0	To support site outage
27/01/2022	30/01/2022	Napier Road (Receipt)	6.0	To support upcoming site ESD day
26/01/2022	27/01/2022	Franklin Road	13.0	To support Max Pressure ATS
26/01/2022	26/01/2022	Franklin Road	7.0	To support Max Pressure ATS
18/01/2022	20/01/2022	TRB (Receipt)	1.0	Support administrative issue 19/01/2022
08/01/2022	07/01/2022	Therang 3	1.0	Support system shutdown 26/12/22
07/12/2021	08/12/2021	Therang 3	5.0	Support for compressor issues 07/12/2021
05/12/2021	06/12/2021	Napier Rd (Delivery)	3.0	Support well start up 05/12/2021
03/12/2021	03/12/2021	Onara	4.0	Support wells returning to service from outage 30/11/2021
01/12/2021	02/12/2021	Onara	5.0	Support well startup from unplanned outage 30/11/2021
01/12/2021	01/12/2021	Onara	8.1	Support unplanned outage 30/11/2021
30/11/2021	01/12/2021	Napier Rd (Delivery)	3.0	Support controlled reduction in area following containment 30/11/2021
29/11/2021	30/11/2021	Onara	6.0	Support operational issue after well start up 29/11/2021
19/11/2021	20/11/2021	Napier Rd (Receipt)	1.5	Support well maintenance/asset
19/11/2021	19/11/2021	Onara	2.5	Support well maintenance/asset
18/11/2021	19/11/2021	Napier Rd (Receipt)	1.5	Support well maintenance/asset
11/11/2021	12/11/2021	Therang 3	5.0	Support for plant start and compressor outage 11/11/2021
11/11/2021	12/11/2021	Napier Rd (Delivery)	5.0	Support operational issues after Max gas clean up 11/11/2021
01/11/2021	01/11/2021	Onara	1.0	Support unplanned outage and gas result 01/11/2021
01/11/2021	01/11/2021	Therang 3	7.0	Support operational issue after power outage at M&B 20/11/2021
03/10/2021	03/10/2021	Napier Rd (Delivery)	3.0	Support Pohokura well maintenance 21/10/21
21/09/2021	01/10/2021	Onara	1.0	Support well start up 20/09/2021
20/09/2021	27/09/2021	Napier Rd (Receipt)	2.0	Support Pohokura well maintenance/asset operation 20/09/2021
20/09/2021	27/09/2021	Onara	2.0	Support Pohokura well maintenance/asset operation 20/09/2021
14/10/2021	15/10/2021	Napier Rd (Receipt)	2.5	Support operational issue with well start up 14/10/2021
08/10/2021	08/10/2021	Therang 3	4.0	Support well maintenance operation 08/10/2021
04/10/2021	05/10/2021	Napier Rd (Receipt)	2.0	Support well maintenance operation 04/10/2021
03/10/2021	04/10/2021	Napier Rd (Receipt)	1.5	Support well startup operation 03/10/2021
02/10/2021	03/10/2021	Onara	4.0	Support unplanned outage and gas result 02/10/2021
01/10/2021	02/10/2021	Napier Rd (Receipt)	2.5	Support well maintenance operation 01/10/2021
19/09/2021	21/09/2021	Napier Rd (Receipt)	4.0	Support well startup during after maintenance
14/09/2021	14/09/2021	Onara	5.0	Support unplanned outage 13/09/21
13/09/2021	14/09/2021	Onara	5.0	Support imbalance caused by Onara unplanned outage 13/09/21
04/09/2021	05/09/2021	Therang 3	10.0	Support unplanned outage 04/09/21
03/09/2021	03/09/2021	Onara	1.5	Support well shutdown operation 02/09/21
21/08/2021	31/08/2021	Onara	1.0	Support operational issues after heavy rain 24/08/2021
21/08/2021	25/08/2021	Napier Rd (Delivery)	4.0	Support plant startup on 23/08/2021
16/08/2021	17/08/2021	Onara	1.0	Support operational issues after well shutdown 16/08/2021
14/08/2021	15/08/2021	Napier Rd (Receipt)	1.4	Support operational issues 14/8/21
14/08/2021	15/08/2021	Therang 2	1.4	Support operational issues 14/8/21
14/08/2021	15/08/2021	Onara	1.5	Support operational issues 14/8/21
01/08/2021	02/08/2021	Onara	3.0	Support operational issues after station trip 1/08/2021
01/08/2021	03/08/2021	Onara	1.0	Support operational issues after well start up 01/08/2021
30/07/2021	31/07/2021	Onara	3.0	Support operational issues after well shutdown 30/07/2021
21/07/2021	22/07/2021	Onara	3.0	Support operational issues after well start up 21/07/2021
20/07/2021	20/07/2021	Onara	4.0	Support operational issues after well start up 20/07/2021
18/07/2021	19/07/2021	Napier Rd (Receipt)	2.0	Support for operational issues 18/07/2021
18/07/2021	19/07/2021	Hurry Power Station	11.0	Support for unit trip and status issues 18/07/2021
11/07/2021	13/07/2021	Therang 3	3.0	Support for operational issues 13/07/2021
12/07/2021	13/07/2021	Onara	3.5	Support for operational issues after well start up 12/07/2021
11/07/2021	12/07/2021	Onara	1.1	Support for operational issues 11/07/2021
02/07/2021	02/07/2021	Onara	2.0	Support for operational issues after well start up 02/07/2021
30/06/2021	01/07/2021	Onara	2.0	Support for operational issues after well start up 30/06/2021
30/06/2021	03/07/2021	Barnard Rd	3.0	Support for ROIL changes due to maintenance operations
29/06/2021	30/06/2021	Onara	4.1	Support operational issues after station trip 29/06/2021
29/06/2021	29/06/2021	Onara	2.0	Support operational issues after well start up 29/06/2021
23/06/2021	23/06/2021	Onara	2.1	Support for operational issues after well start up 23/06/2021
23/06/2021	23/06/2021	Therang 2	1.2	Support for incorrect trade calculation
22/06/2021	22/06/2021	Therang 3	1.1	Support for incorrect trade calculation
22/06/2021	22/06/2021	Onara	2.8	Support for operational issues after well start up 21/06/2021
15/06/2021	15/06/2021	Onara	10.0	Support for unplanned outage 15/06/2021
15/06/2021	16/06/2021	Onara	11.0	Support for operational issue 15/06/2021
14/06/2021	15/06/2021	Onara	3.0	Support for unplanned outage 14/06/2021
14/06/2021	15/06/2021	Napier Rd (Receipt)	1.1	Support plant startup issue after trip 14/06/2021
13/06/2021	14/06/2021	Onara	4.0	Support operational issues after well start up 13/06/2021
12/06/2021	13/06/2021	Onara	3.0	Support for high pressure & well startup issue 12/06/2021
09/06/2021	10/06/2021	Therang 3	2.5	Support for operational issues 09/06/2021
08/06/2021	09/06/2021	Napier Rd (Receipt)	2.1	Support to keep plant running at minimum rates
7/06/2021	8/06/2021	Napier Rd (Delivery)	5.0	Support operational issues 07/06/2021
27/05/2021	28/05/2021	Onara	1.0	Support for unplanned outage 27/05/2021
22/05/2021	24/05/2021	Onara	5.0	Support for unplanned outage 22/05/2021
21/05/2021	22/05/2021	Onara	2.8	Support for ROIL changes due to maintenance operations
20/05/2021	21/05/2021	Onara	3.8	Support operational issues after station trip 20/05/2021
19/05/2021	20/05/2021	Onara	7.0	Support for start status issue 19/05/2021
18/05/2021	19/05/2021	Onara	1.1	Support imbalance caused by Pohokura unplanned outage 18/05/2021
18/05/2021	18/05/2021	Napier Rd (Receipt)	3.0	Support unplanned outage 18/05/21
17/05/2021	17/05/2021	Napier Rd (Receipt)	2.0	Support operational issues 17/05/21
16/05/2021	16/05/2021	Therang 3 (Receipt)	6.0	Support for GATS issues 16/05/2021
24/04/2021	25/04/2021	Therang 1	5.0	Support for plant outage 24/04/2021
22/04/2021	22/04/2021	Napier Rd (Receipt)	1.2	Support planned outage 22/04/2021
11/04/2021	11/04/2021	Onara	3.0	Support for operational issues 11/04/2021
07/04/2021	08/04/2021	Onara	1.2	Support for operational issues 07/04/2021
21/03/2021	31/03/2021	Therang 3	2.5	Support for operational issues 31/03/2021
31/03/2021	31/03/2021	Onara	1.5	Support for operational issues 31/03/2021
30/03/2021	30/03/2021	Therang 3	3.5	Support for operational issues from power outage 30/03/21
29/03/2021	29/03/2021	Therang 3	1.0	Support for operational issues 29/03/2021
26/03/2021	27/03/2021	Onara	3.0	Support for operational issues 26/03/2021
25/03/2021	26/03/2021	Onara	2.0	Support for plant startup issues 25/03/2021
17/03/2021	18/03/2021	Onara	2.0	Support for plant startup 17/03/2021
16/03/2021	16/03/2021	Onara	5.0	Support for plant startup 16/03/2021
15/03/2021	15/03/2021	Therang 3	2.0	Support for operational issues 15/03/2021
15/03/2021	15/03/2021	Onara	2.0	Support for operational issues 15/03/2021
01/03/2021	02/03/2021	Onara	1.1	Support for operational issues 01/03/21
28/02/2021	28/02/2021	Barnard Rd	1.5	Support unplanned outage 28/02/2021
28/02/2021	28/02/2021	Full Road	1.0	Support unplanned outage 28/02/2021
28/02/2021	28/02/2021	Onara	3.0	Support unplanned outage 28/02/2021
28/02/2021	28/02/2021	Napier Rd (Delivery)	2.0	Support for unplanned outage 28/02/2021
28/02/2021	28/02/2021	Napier Rd (Receipt)	12.0	Support unplanned outage 28/02/2021
28/02/2021	28/02/2021	Onara	6.0	Support for operational issues 28/02/21
28/02/2021	28/02/2021	Onara	3.0	Support for operational issues 28/02/21
17/02/2021	17/02/2021	Onara	3.0	Support operational issues 17/02/2021
09/02/2021	09/02/2021	Onara	2.0	Support for operational issues 09/02/21
04/02/2021	05/02/2021	Therang 3 (Receipt)	3.3	Support for operational issues 04/02/2021
21/01/2021	31/01/2021	Onara	2.5	Support for operational issues 31/01/2021
21/01/2021	22/01/2021	Onara	5.0	Support for operational issues 22/01/2021
21/01/2021	22/01/2021	Therang 3 (Receipt)	9.0	Support for operational issues 21/01/2021
21/01/2021	22/01/2021	Therang 3	5.0	Support for operational issues 21/01/2021
21/01/2021	22/01/2021	Franklin Road	6.0	Support for operational issues 21/01/2021
21/01/2021	22/01/2021	Onara	1.5	Support for operational issues 21/01/2021
17/01/2021	18/01/2021	Therang 3 (Receipt)	3.0	Support for operational issues 17/01/2021
17/01/2021	18/01/2021	Therang 3 (Receipt)	3.0	Support for operational issues 17/01/2021
23/12/2020	24/12/2020	Onara	2.0	Support for operational issues 23/12/2020
23/12/2020	24/12/2020	Napier Rd (Delivery)	2.0	Support for operational issues 23/12/2020
21/12/2020	21/12/2020	Therang 3 (Receipt)	2.0	Support for restoration of conditions after station trip
01/12/2020	02/12/2020	Therang 3 (Receipt)	5.0	Support for restoration of conditions after station trip
01/12/2020	02/12/2020	Onara	2.0	Support for station 01/12/2020
01/12/2020	02/12/2020	Napier Rd (Receipt)	1.5	Support operational issues 01/12/2020
01/12/2020	02/12/2020	Onara	1.5	Support operational issues 01/12/2020
01/12/2020	02/12/2020	Napier Rd (Receipt)	5.0	Support operational issues 01/12/2020
01/12/2020	02/12/2020	Onara	1.0	Support for well start up
01/12/2020	02/12/2020	Franklin Road	4.0	Support for well start up
29/11/2020	30/11/2020	Therang 3 (Receipt)	2.0	Support for well start up
29/11/2020	30/11/2020	Onara	6.0	Support for restoration of conditions after station trip
29/11/2020	30/11/2020	Napier Rd (Receipt)	17.0	Support for operational issues 29/11/2020
29/11/2020	30/11/2020	Napier Rd (Receipt)	2.0	Support for unplanned outage 29/11/2020
24/11/2020	25/11/2020	Onara	2.5	Support for operational issues 24/11/2020
24/11/2020	25/11/2020	Napier Rd (Receipt)	2.5	Support for operational issues 24/11/2020
17/11/2020	18/11/2020	Napier Rd (Receipt)	4.0	Support for Well start up
13/11/2020	14/11/2020	Mangoni	5.0	Support to outage 13/11/2020
13/11/2020	14/11/2020	Hurry Power Station	4.0	Support to outage 13/11/2020
13/11/2020	14/11/2020	Napier Rd (Receipt)	5.0	Support to outage 13/11/2020
05/11/2020	06/11/2020	Napier Rd (Receipt)	5.0	Support to outage 05/11/2020
04/11/2020	05/11/2020	Napier Rd (Receipt)	3.0	Support to outage 05/11/2020
19/10/2020	19/10/2020	Napier Rd (Receipt)	2.0	Support to keep plant running at minimum rates
18/10/2020	19/10/2020	Barnard Rd	3.0	Support to keep plant running at minimum rates
24/09/2020	25/09/2020	Franklin Road	3.0	Non-Business Day (D-1) was not run
24/09/2020	25/09/2020	Robrow	5.0	Non-Business Day (D-1) was not run
21/09/2020	22/09/2020	Onara	3.5	Support for restoration of conditions after station trip
09/09/2020	10/09/2020	Onara	3.0	Support for Well start up
8/09/2020	9/09/2020	Onara	4.5	Support for Well start up
04/09/2020	05/09/2020	Therang 3 (Receipt)	6.0	Support for restoration of conditions after station trip
4/09/2020	5/09/2020	Therang 3	7.0	Support for restoration of conditions after station trip
01/09/2				

15/11/2019	16/11/2019	Therung # 3 (Receipt)	23.0	Support for restoration of conditions after station trip
30/10/2019	31/10/2019	Therung # 2	6.0	Support for Incident remediation error
01/10/2019	02/10/2019	Franklin Road	7.0	Support for restoration of pipeline conditions
01/10/2019	02/10/2019	Therung # 3 (Receipt)	4.0	Support for restoration of conditions after station trip
13/09/2019	13/09/2019	Therung # 2	12.0	Support for pipeline management
09/09/2019	10/09/2019	Onana	6.0	Support for restoration of conditions after station trip
14/08/2019	15/08/2019	Ngiamara Rd (Receipt)	7.0	Support for high pressure and high tripping
14/08/2019	15/08/2019	Onana	2.0	Support for high pressure and high tripping
11/08/2019	12/08/2019	Paluru	4.0	Support for pipeline management for lost corners
08/08/2019	11/08/2019	Paluru	2.0	Support for pipeline management for lost corners
03/08/2019	04/08/2019	Onana	5.0	Support for planned plant outage
01/08/2019	02/08/2019	Onana	3.0	Support for planned plant outage
30/07/2019	31/07/2019	Onana	2.0	Support for planned plant outage
19/07/2019	20/07/2019	Therung # 2	4.0	Support for restoration of conditions after station trip
19/07/2019	21/07/2019	Onana	5.0	Support for restoration of conditions after station trip to seal Neadmaru Rd (Receipt)
19/07/2019	21/07/2019	Ngiamara Rd (Receipt)	9.0	Support for restoration of conditions after station trip
19/07/2019	20/07/2019	Therung # 1 (Receipt)	6.0	Support for restoration of conditions after station trip
29/06/2019	29/06/2019	Therung # 3 (Receipt)	3.0	Support for restoration of conditions after station trip
15/06/2019	15/06/2019	Therung # 3 (Receipt)	3.0	Support for restoration of conditions after station trip
09/06/2019	10/06/2019	Ngiamara Rd (Receipt)	5.0	Support for restoration of conditions after station trip
01/06/2019	02/06/2019	Ngiamara Rd (Receipt)	4.0	Support for restoration of conditions after station trip
08/06/2019	09/06/2019	Onana	5.0	Support for restoration of conditions after station trip
04/06/2019	05/06/2019	Ngiamara Rd (Receipt)	5.0	Planned maintenance outage
02/06/2019	03/06/2019	Paluru	5.0	Lighting while stopped communications NTU / metering
01/06/2019	02/06/2019	Onana	2.0	Support for plant re-start
01/06/2019	02/06/2019	Onana	20.0	Lighting while stopped communications NTU / metering
01/06/2019	02/06/2019	Onana	2.0	Support for plant re-start
31/05/2019	01/06/2019	Paluru	10.0	Lighting while stopped communications NTU / metering
31/05/2019	01/06/2019	Ngiamara Rd (Receipt)	3.0	Support for plant re-start
29/05/2019	29/05/2019	Therung # 2	2.0	Support for planned Pohokura PPS re-start
29/05/2019	31/05/2019	Ngiamara Rd (Receipt)	19.0	Support for planned Pohokura PPS re-start
19/05/2019	19/05/2019	Onana	19.0	Support for plant re-start
19/05/2019	14/05/2019	Therung # 3 (Receipt)	2.0	Support for restoration of conditions after station trip
07/05/2019	07/05/2019	Onana	4.0	Planned maintenance outage
06/05/2019	06/05/2019	Ngiamara Rd (Receipt)	6.0	Planned maintenance outage
05/05/2019	04/05/2019	Ngiamara Rd (Receipt)	6.0	Planned maintenance outage
04/05/2019	04/05/2019	Ngiamara Rd (Receipt)	6.0	Planned maintenance outage
29/04/2019	29/04/2019	Paluru	6.0	Support for restoration of conditions after station trip
29/04/2019	29/04/2019	Onana	6.0	Support for restoration of conditions after station trip
29/04/2019	29/04/2019	Ngiamara Rd (Receipt)	5.0	Support for restoration of conditions after station trip
01/04/2019	02/04/2019	Ngiamara Rd (Receipt)	4.0	Planned maintenance
29/03/2019	30/03/2019	Onana	7.0	Support for restoration of conditions after station trip
29/03/2019	27/03/2019	Onana	15.0	Planned maintenance outage
26/03/2019	26/03/2019	Onana	7.0	Planned maintenance outage
23/03/2019	24/03/2019	Onana	5.0	Planned maintenance outage
18/03/2019	18/03/2019	Ngiamara Rd (Receipt)	4.0	Support for restoration of conditions after station trip
18/03/2019	22/03/2019	Onana	4.0	Support for restoration of conditions after station trip
17/03/2019	17/03/2019	Ngiamara Rd (Receipt)	4.0	Support for restoration of conditions after station trip
16/03/2019	16/03/2019	Ngiamara Rd (Receipt)	6.0	Support for restoration of conditions after station trip
15/03/2019	15/03/2019	Ngiamara Rd (Receipt)	6.0	Support for restoration of conditions after station trip
14/03/2019	12/03/2019	Ngiamara Rd (Receipt)	10.0	Support for restoration of conditions after station trip
13/03/2019	12/03/2019	Onana	10.0	Support for restoration of conditions after station trip
09/03/2019	09/03/2019	Onana	5.0	Support for restoration of conditions after station trip
08/03/2019	08/03/2019	Ngiamara Rd (Receipt)	7.0	Support for restoration of conditions after station trip
08/03/2019	08/03/2019	Onana	7.0	Support for restoration of conditions after station trip
07/03/2019	07/03/2019	Onana	7.0	Support for restoration of conditions after station trip
06/03/2019	07/03/2019	Ngiamara Rd (Receipt)	15.0	Support for restoration of conditions after station trip
05/03/2019	05/03/2019	Onana	5.0	Support for restoration of conditions after station trip
04/03/2019	05/03/2019	Onana	5.0	Support for plant re-start
26/02/2019	26/02/2019	Therung # 3 (Receipt)	4.0	Support for restoration of conditions after station trip
24/02/2019	25/02/2019	Onana	6.0	Planned maintenance outage
23/02/2019	23/02/2019	Ngiamara Rd (Receipt)	15.0	Support for plant re-start
22/02/2019	22/02/2019	Franklin Road	4.0	Support for plant re-start
21/02/2019	21/02/2019	Therung # 1 (Receipt)	2.0	Support for restoration of conditions after station trip
31/12/2018	31/12/2018	Paluru	7.0	Incident O2 enrichment in OATIS due to Trickle
14/12/2018	15/12/2018	Ngiamara Rd (Receipt)	4.0	Support for high pressure and high tripping
14/12/2018	15/12/2018	Paluru	6.0	Support for high pressure and high tripping
14/12/2018	15/12/2018	Therung # 3 (Receipt)	8.0	Support for restoration of conditions after station trip
13/12/2018	13/12/2018	Onana	10.0	Incident O2 enrichment in OATIS due to Trickle
11/12/2018	11/12/2018	Ngiamara Rd (Receipt)	5.0	Support for restoration of pipeline conditions
04/12/2018	10/12/2018	Ngiamara Rd (Receipt)	20.0	Support for restoration of pipeline conditions
04/12/2018	04/12/2018	Onana	5.0	Support for restoration of pipeline conditions
28/11/2018	29/11/2018	Franklin Road	5.0	Non-Business Day (D-1 was not set)
28/11/2018	29/11/2018	Onana	5.0	Non-Business Day (D-1 was not set)
28/11/2018	29/11/2018	Therung # 3 (Receipt)	4.0	Support for restoration of conditions after station trip
09/10/2018	10/10/2018	Ngiamara Rd (Receipt)	3.0	Support for restoration of pipeline conditions
08/10/2018	09/10/2018	Ngiamara Rd (Receipt)	6.0	Support for plant re-start
05/09/2018	06/09/2018	Ngiamara Rd (Receipt)	6.0	Support for Piping
05/09/2018	06/09/2018	Therung # 2	3.0	Support for Piping
11/07/2018	14/07/2018	Ngiamara Rd (Receipt)	3.0	Support for restoration of station
11/07/2018	14/07/2018	Ngiamara Rd (Receipt)	3.0	Support for restoration of station
11/07/2018	22/07/2018	Onana	6.0	Support for plant re-start
19/06/2018	19/06/2018	Franklin Road	3.0	Support for restoration of conditions after station trip
17/05/2018	18/05/2018	Therung # 3 (Receipt)	2.0	Support for restoration of conditions after station trip
08/05/2018	08/05/2018	Onana	10.0	Support for high pressure and high tripping
23/04/2018	24/04/2018	Therung # 2 (Receipt)	15.0	Support for plant re-start
19/04/2018	22/04/2018	Ngiamara Rd (Receipt)	3.0	Support for Piping
19/04/2018	22/04/2018	Onana	3.0	Support for Piping
09/03/2018	11/03/2018	Onana	10.0	Planned maintenance outage
15/03/2018	16/03/2018	Onana	10.0	Planned maintenance outage
13/03/2017	13/03/2017	Therung # 3 (Receipt)	10.0	Support for restoration of conditions after station trip
11/12/2017	11/12/2017	Therung # 3 (Receipt)	5.0	Support for restoration of conditions after station trip
05/11/2017	05/11/2017	Onana	6.0	Support for restoration of pipeline conditions
27/10/2017	27/10/2017	Therung # 3 (Receipt)	6.0	Support for restoration of conditions after station trip
27/10/2017	27/10/2017	Therung # 2	2.0	Support for restoration of conditions after station trip
23/10/2017	23/10/2017	Ngiamara Rd (Receipt)	2.0	Support for restoration of conditions after station trip
09/10/2017	09/10/2017	Therung # 2 (Receipt)	21.0	Support for planned plant outage
29/09/2017	29/09/2017	Therung # 2	4.0	Support for restoration of conditions after station trip
06/09/2017	06/09/2017	Ngiamara Rd (Receipt)	7.0	Support for restoration of conditions after station trip
30/08/2017	30/08/2017	Therung # 3 (Receipt)	7.0	Support for restoration of conditions after station trip
16/08/2017	16/08/2017	Therung # 3 (Receipt)	2.0	Support for restoration of conditions after station trip
20/07/2017	20/07/2017	Therung # 3 (Receipt)	4.0	Support for restoration of conditions after station trip
20/07/2017	20/07/2017	Therung # 2	2.0	Support for restoration of conditions after station trip
20/06/2017	20/06/2017	Onana	8.0	Support for restoration of conditions after station trip
20/06/2017	20/06/2017	Onana	12.0	Support for restoration of conditions after station trip
19/06/2017	19/06/2017	Therung # 2	8.0	Support for restoration of conditions after station trip
19/06/2017	19/06/2017	Therung # 2	3.0	Support for restoration of conditions after station trip
01/06/2017	01/06/2017	Ngiamara Rd (Receipt)	10.0	Support for restoration of conditions after station trip
31/05/2017	31/05/2017	Ngiamara Rd (Receipt)	30.0	Support for restoration of conditions after station trip
01/05/2017	15/05/2017	Ngiamara Rd (Receipt)	4.0	Support for planned plant outage
18/04/2017	18/04/2017	Franklin Road	2.0	Incidents due to some allocation gates behind the Waiata Point
17/04/2017	17/04/2017	Onana	2.0	Incidents due to some allocation gates behind the Waiata Point
02/04/2017	02/04/2017	Onana	3.0	Support for restoration of conditions after station trip
24/03/2017	24/03/2017	Franklin Road	12.0	Site communication issue
15/03/2017	15/03/2017	Onana	5.0	Support for restoration of pipeline conditions
08/03/2017	08/03/2017	Onana	5.0	Support for restoration of pipeline conditions
14/03/2017	14/03/2017	Onana	2.0	Support for plant re-start
10/03/2017	10/03/2017	Onana	5.0	Support for restoration of conditions after station trip
30/01/2017	30/01/2017	Onana	23.0	Support for planned plant outage
29/01/2017	29/01/2017	Onana	1.0	Support for restoration of conditions after station trip
02/01/2017	02/01/2017	Ngiamara Rd (Receipt)	2.0	Support for restoration of pipeline conditions
01/01/2017	01/01/2017	Therung # 2	6.0	Support for restoration of pipeline conditions
29/12/2016	29/12/2016	Therung # 3 (Receipt)	3.0	Support for restoration of conditions after station trip
29/12/2016	29/12/2016	Onana	3.0	Support for restoration of conditions after station trip
20/12/2016	20/12/2016	Onana	17.0	Support for restoration of pipeline conditions
05/12/2016	15/12/2016	Ngiamara Rd (Receipt)	6.0	Support for restoration of conditions after station trip
15/12/2016	15/12/2016	Therung # 3 (Receipt)	2.0	Support for restoration of conditions after station trip
09/12/2016	15/12/2016	Therung # 2	2.0	Support for restoration of conditions after station trip
23/11/2016	23/11/2016	Franklin Road	1.0	Support for pipeline management
23/11/2016	23/11/2016	Paluru	2.0	Support for pipeline management
01/11/2016	01/11/2016	Onana	17.0	Support for restoration of conditions after station trip
01/11/2016	01/11/2016	Franklin Road	2.0	Support for planned plant outage
20/10/2016	20/10/2016	Ngiamara Rd (Receipt)	12.0	Support for restoration of conditions after station trip
19/10/2016	20/10/2016	Therung # 2	3.0	Support for restoration of conditions after station trip
15/10/2016	15/10/2016	Onana	12.0	Incidents by Access OATIS
15/10/2016	15/10/2016	Paluru	4.0	Incidents by Access OATIS
15/09/2016	15/09/2016	Ngiamara Rd (Receipt)	5.0	Support for planned plant outage
15/09/2016	15/09/2016	Onana	7.0	Support for planned plant outage
01/09/2016	01/09/2016	Franklin Road	6.0	Support for Piping
01/09/2016	01/09/2016	Paluru	6.0	Support for Piping
31/08/2016	31/08/2016	Paluru	7.0	Support for Piping
31/08/2016	31/08/2016	Therung # 3 (Receipt)	3.0	Support for restoration of conditions after station trip
05/08/2016	06/08/2016	Therung # 2	2.0	Support for restoration of conditions after station trip
27/07/2016	27/07/2016	Ngiamara Rd (Receipt)	7.0	Support for planned plant outage
26/07/2016	26/07/2016	Therung # 2	5.0	Support for restoration of conditions after station trip
26/05/2016	26/05/2016	Therung # 2	5.0	Support for restoration of conditions after station trip
26/05/2016	26/05/2016	Ngiamara Rd (Receipt)	5.0	Support for restoration of conditions after station trip
24/05/2016	24/05/2016	Onana	3.0	Accommodate Onana support during the Critical Contingency event
17/05/2016	17/05/2016	Therung # 2	5.0	Support for plant re-start
17/05/2016	17/05/2016	Therung # 2	6.0	Support for plant re-start
17/05/2016	17/05/2016	Therung # 3 (Receipt)	8.0	Support for plant re-start
17/05/2016	17/05/2016	Ngiamara Rd (Receipt)	12.0	Support for plant re-start
07/05/2016	07/05/2016	Therung # 2	2.0	Support for plant re-start
27/04/2016	27/04/2016	Therung # 2	7.0	Support for plant re-start
27/04/2016	27/04/2016	Therung # 3 (Receipt)	7.0	Support for plant re-start
20/04/2016	20/04/2016	Paluru	11.0	OATIS outage affecting re-try cycles
10/04/2016	10/04/2016	Hurry Power Station	3.0	OATIS outage affecting re-try cycles
09/04/2016	09/04/2016	Franklin Road	4.0	OATIS outage affecting re-try cycles
09/04/2016	09/04/2016	Franklin Road	5.0	OATIS outage affecting re-try cycles
09/04/2016	09/04/2016	Paluru	4.0	OATIS outage affecting re-try cycles
05/04/2016	05/04/2016	Ngiamara Rd (Receipt)	5.0	Support for restoration of conditions after station trip
20/03/2016	20/03/2016	Onana	2.0	Support for planned Pohokura PPS re-start
20/03/2016	20/03/2016	Therung # 2	25.0	Support for planned Pohokura PPS re-start
19/03/2016	19/03/2016	Ngiamara Rd (Receipt)	24.0	Support for planned Pohokura PPS re-start
19/03/2016	19/03/2016	Onana	21.0	Support for planned Pohokura PPS re-start
19/03/2016	19/03/2016	Therung # 2	4.0	Support for planned Pohokura PPS re-start
19/03/2016	19/03/2016	Ngiamara Rd (Receipt)	4.0	Support for planned Pohokura PPS re-start
09/03/2016	10/03/2016	Ngiamara Rd (Receipt)	23.0	Support for planned Decontamination/Recontamination of pipeline
09/03/2016	10/03/2016	Franklin Road	2.0	Support for planned Decontamination/Recontamination of pipeline
04/03/2016	09/03/2016	Ngiamara Rd (Receipt)	10.0	Support for planned Decontamination/Recontamination of pipeline
03/03/2016	03/03/2016	Therung # 2	9.0	Support for restoration of conditions after station trip
29/02/2016	29/02/2016	Therung # 3 (Receipt)	5.0	Support for restoration of conditions after station trip
29/02/2016	29/02/2016	Therung # 2	5.0	Support for restoration of conditions after station trip
29/02/2016	29/02/2016	Therung # 3 (Receipt)	5.0	Support for restoration of conditions after station trip
05/02/2016	05/02/2016	Paluru	8.0	Support for restoration of conditions after station trip
05/02/2016	05/02/2016	Paluru	5.0	Support for restoration of conditions after station trip
21/01/2016	21/01/2016	Ngiamara Rd (Receipt)	5.0	Onsite production facility return to service from Force Majeure shutdown
15/01/2016	15/01/2016	Onana	6.0	Onsite production facility return to service from Force Majeure shutdown
16/12/2015	16/12/2015	Therung # 2	4.0	Support for planned Pohokura PPS re-start
16/12/2015	16/12/2015	Therung # 3 (Receipt)	3.0	Support for restoration of conditions after station trip
16/12/2015	16/12/2015	Therung # 2	8.0	Support for restoration of conditions after station trip
16/12/2015	16/12/2015	Ngiamara Rd (Receipt)	11.0	Support for planned Pohokura PPS re-start
09/12/2015	09/12/2015	Ngiamara Rd (Receipt)	20.0	Facilities for approved OPH
29/11/2015	29/11/2015	Onana	2.0	Pre-approved line for approved OPH on 30/11/2015
29/11/2015	30/11/2015	Onana	1.0	Pre-approved line for approved OPH on 30/11/2015
18/10/2015	18/10/2015	Paluru	2.0	Approved maintenance hot flow trial
18/10/2015	18/10/2015	Paluru	3.0	Approved maintenance hot flow trial
18/10/2015	18/10/2015	Paluru	4.0	Approved maintenance hot flow trial
18/10/2015	18/10/2015	Paluru	4.0	Approved maintenance hot flow trial
18/10/2015	18/10/2015	Paluru	4	